

Leaver steel tool for big lathe 7.00

one roof for big lathe 2.00

3. $4\frac{7}{8}$ X 15 in. plain plugs

5. $4\frac{7}{8}$ X 24 14 X 7

5. $4\frac{7}{8}$ X 24 plain plugs

7. $6\frac{1}{4}$ X 24 7 11 X 7

13. $6\frac{1}{4}$ X 24 plain

3. 7 X 24

13. Full wheel shifts 12.00

1 grind stone condition good

1 big lathe

1 flexible lever

1 small lathe

1 vice

1 hand saw

1 planer

1 swinging saw table good

can sit. sawing table

1 rip saw

One jointer Can good

12 small saws Can Medium

3 hand saws " Good

1 - bar

130 - H. P. Sargent

4 emery wheels

1 stand

1 chair full

1 wood jointer

1 fore plane

1 jack plane

2 long iron

1 smooth plane

3. $\frac{3}{4}$ auger

2. $\frac{1}{2}$

1 - 3

2 saw clamps

1 level

1 roof shovel

1 rabbit lathe

1 short saw

Inventory continued

1 - bit stock 1 cant hook

2 wrenches 1 hand punch

1 square 1 adp.

1 sledge 1 turning tool

1 man saw 1 nail set

5 small gouges 50 ft 12 in. belt condition medium

1 - 2 in auger 24 " 3 " " leather

1 wood rasp 20 " 4 " " gander

1 - 2 in chisel 32 " 5 " " rubber good

4 bits for driving rack 30 feet birch leather medium

2 hammers 30 " " " good

2 little wrenches 30 " " " rubber poor

2 pair caliper 40 " 4 " " gander

1 draw shovel 30 " 6 " " rubber