

1 - 5-3/16 Wilson Elevator,
 2 sets of links for Wilson elevators
 1 - Spider & Slips from 15 1/2 to 5-3/16
 1 - 10" underreamer union,
 4 sets of cutters,
 1 - set of 12 1/2" cutters for Grant underreamer,
 2 - Moon Generators,
 1 - Star Blower,
 1 - Forge,
 1 - Underreamer Anvil, 450 lbs.
 90 ft 12" drilling belt,
 1 - steel tempering trough,
 1 - Lift jack,
 600 ft. light wire,
 950 ft. 1" casing line,
 800 ft. 1" drilling line.
 1000 ft. 7/8 drilling line,
 1 - 3500 at 7/8" drilling line.

Ex.A 4.

(List of tools, continued)/

3500 feet of 5/8" Sand Line.
 400 ft. 2" line pipe,
 600 ft. 1" line pipe.
 100 ft. 3.8 pipe,
 3 oil well supply lubricators,
 2 - Cross Head pumps,
 10 - sets of slips for combination sockets,
 1 - set 2" lay tongs
 1 - 15 1/2 Baker Pipe shoe,
 1 - set 12 1/2" casing clamps,
 3 - Bull rope mules,
 3 - 350 ft. 3/4 rope,
 1 - 2 1/2" jerk line,
 4 dozen electric light bulbs,
 2 - steel tool boxes,
 1 - set of augers from 2 1/2 to 3/8
 2 - sets of pipe dyes,
 1 - pipe vise,
 3 - pipe cutters,
 3 - 24" Stilson Pipe wrenches,
 2 - 36" Stilson pipe wrenches,
 4 - 18" Stilson pipe wrenches,
 3 - screw drivers,
 1 - combination wrench,
 3 - hand saws,
 1 - cross cut saw,
 6 - coal chisels,
 3 - hatchets,
 4 - splitting chisels,
 1 - 3/4 spool roller,