Slip Sockets.

4 - 84" Slip Sockets.

Rope Sockets.

l Wire line rope Socket, 5 - 32" Neck Rope Sockets, 15 - 32" Neck Rope Sockets. Boilers.

9 Unmounted Oil Well Sumply Company Boilers, 25 Horse Power, 1 Mounted Oil Well Supply Company boiler, 25 Horse Power, #25130, 1 Unmounted Golley & Finley Boiler, 25 Horse Power, 1 Unmounted Bovaird & Seyfang Boiler, 25 Horse Power, #2102,

Engines.

8 - 10½ x 12 Oil Well Supply Co. Engines Complete with Balance, # 5635, 4681, 5680, 5668, 5624, 5574, 1 - 11 x 12 Oil Well Supply Company Engine Complete with balance, 1-1/4 x 12 Oil Well Supply Company singlest contributional balance, 1-1/4 X Ajax Engine complete with balance, 1 - 10 x 12 Oil Well Supply Company Engine # 4761.

Stems.

12. 4 5 " x 36' Stems, $3\frac{1}{4}$ " x $4\frac{1}{4}$ " Pin, 8 - $4\frac{1}{2}$ " x 36' Stems, $2\frac{3}{4}$ " x $3\frac{3}{4}$ " Pin, 1 - $3\frac{3}{4}$ " x 25' Stem, $2\frac{1}{4}$ " x $3\frac{1}{4}$ " Pin, 2 - 5" x 32 ' Stems, 3" x 4 " Pin,, 3 - $4\frac{1}{4}$ " x 36' Stems, $2\frac{3}{4}$ " x $3\frac{3}{4}$ " Pin, 1 - 5 " x 33' Stem, $2\frac{3}{4}$ " x $3\frac{3}{4}$ " Pin, - 1 - 4" x 20' Stem, 2" x 3" Pin.

Wire Casing Lines.

1 - 7/8 " x 500' Wire Casing Line, 1 - 1" x 28' Dead Line, 1 - 1" x 20' Dead Line, 2 - $\frac{2}{4}$ " x 350' Wire Casing Line. 1 - $\frac{3}{4}$ " x 200' Wire Casing Line.

Casing Blocks.

5 Double Steel Blocks, 26", 3 Single Steel Blocks, 26", 1 Single Steel Block, 10" Casing Hooks.

3 - 90# Casing Hooks, 2 - 60# Casing Hooks, 2 - 120# Casing Hooks.

Tool Gauges.

1 - 13" Tool Gauges, 11 - 10" Tool Gauges, 4 - 8\frac{1}{2}" Tool Gauges, 13 - 6\frac{1}{2}" Tool Gauges, 8 - 8"

Tool Gauges, 1 - 5 - 5/8" Tool Gauges, 1 - 4-7/8" Tool Gauge, 1 - 4\frac{1}{2}" Tool Gauge.

Oil Savers.

4 - 22" Oil Savers, 1 - Wire Line Oil Saver,

Pipe Taps.

1 - 2" Pipe Taps, 2 - 1" Pipe Taps.

Anvils.

3 Oil Well Supply Company anvils, larger, 3 Small anvils and bridles, 3 large anvils. Trimo Wrenches.

10 - 18" Trimo Wrenches, 1 - 24" Erimo Wrench, 1 - 24 " Trimo Wrench.

Combination Wrenches.

8 - 15" Combination Wrenches, 1 - 10" Combination Wrench, 1 - 8" Combination Wrench.
Augers.

ll - ½ " Beam Augers, 3 - 1" Augers, 4 - 1½" Augers, 7 - 2" Augers, 5 - 1½" Augers. Crumbie Tongs.

6 Sets "2" Crumbie Tongs, 5 Sets 21" Crumbie Tongs.

Tool Boxes.

11 Large Tool Boxes, 1 Small Tool Box.

Miscellaneous.

9 Mattocks, 10 Casing Wagons, 4 - 10" S Wrenches, 5 Rope Knives, 9 Hand Saws, 1 Hack Saw, 3 Squares, 6 Pinch Bars, 1 - 12" Screw Jack, 12 - 3/8" Reverse Rod Pipes, 55 feet each, 12 Derrick Wheels, 12 Reverse Wire Cords, 8 Patent Auger Handles, 5 Never Slip Casing Hooks; 1 Set Temper Screw Clamps, 9 Ball Pene Hammers, 9 Hatchets, 8 Axes, 10 Spudding Shoes, 13-prong grab 21 - 16# Sledges, 3 Wire Clamps, 10 Chain Tongs, 1 Latch Jack, 4 Rope Spears, 6 Jar Knockers,